Work O	rder ID	55898
--------	---------	-------



Page 1

February 4, 2010 8:50:44 AM

Item ID:

D4004-11

Accept



Setup Start



Stop

Revision ID:

Item Name:

Required Date: 2/11/10

Strap Attach Bracket

Start Date:

2/04/10

Start Oty: 2.00

Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date: 10-2-04

Date:

Tooling:

SPC (Y/N):

Date: Date: Run

Start

Stop



Sequence ID/ Work Center ID

Operation Description Set Up/ **Run Hours** Draw Number Draw Rev.

Plan Qty Code

Reject Accept Qty

Reject Number Insp. Stamp

Draw Nbr

Revision Nbr

D4004 A-PRELIM

OC:

100

Bandsaw

BAND SAW

Memo

0.00

0.00

Jeaspa Bandsaw

1-Cut D3033-144 extrusion to length per D4004-11 detail of dwg D4004

Ensure cut is started at correct place per dwg Batch: B 30209

2-Deburr

105

Small Fab

Small Fab

Memo

0.00

0.00

Drill and c'sink holes as per dwg and trim part to lenght as required.

PRELIMINARY ISSUE

Dart A	Aeros	pace	Ltd
--------	-------	------	-----

	•	,							5.
W/O:			WC	RK ORDER CHANG	ES				· · · · · · · · · · · · · · · · · · ·
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									·
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date:	
Resolution:		esolution:	Dispositio	osed:	ed: Date:				
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCF	R)		1	
DATE	STEP	Description of NC	Corrective Action Section B			Verific	cation	Approval	Approval
	J	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector
									!
				-					

Work Order ID 55898

Page 2

February 4, 2010 8:50:44 AM

Item ID:

D4004-11

Revision ID:

Item Name: Strap Attach Bracket

Start Date: Required Date: 2/11/10

2/04/10

Start Qty: 2.00 Req'd Qty: 2.00

Date:_____

Accept

Setup Start

Stop



Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Date: _____

Tooling:

SPC (Y/N):

Date:

Date:

Draw

Rev.

Start



Stop

Sequence ID/ **Work Center ID**

110

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

Set Up/ **Run Hours**

Plan Code

Reject Accept Qty Oty

Run

Reject Number Stamp

Insp.

0.00

120

130

HandFinish

Chemical Conversion Coat per QSI005 4.1

Memo

Memo

Df 10 02-22

Hand Finishing

QC3- Inspect Part Finish

Quality Control

Memo

0.00

=7 m/ w/02/22

Dart	Aeros	pace	Ltd
------	-------	------	-----

									~	
W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector	
								,		
Part No:		PAR #:	Fault Cate	egory:	No DQ	o DQA: Date:				
Resolution:			Disposition: QA: N/C Clos				sed: Date:			
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NC	R)		-		
DATE	STED	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval QC Inspector	
DAIL	SILF	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng		

Work Order ID 55898

Page 3

February 4, 2010 8:50:44 AM

Required Date: 2/11/10

Item ID:

D4004-11

Accept

Setup Start

Stop

Revision ID:

Item Name:

Strap Attach Bracket

Start Date:

2/04/10

Start Qty: 2.00

Req'd Qty: 2.00

Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Date:_____

Date:

Tooling:

SPC (Y/N):

Date: Date: __

Draw

Rev.

Plan

Code

Start Run

Reject

Qty

Stop

Reject

Number

Sequence ID/ Work Center ID

140

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location:

Memo

Set Up/ **Run Hours**

0.00

Qty

Accept

Insp.

Stamp

150

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

BS 10-4-14

POSITIVE RECALL

RELEASED

Dart Aerospac	е	Ltd
---------------	---	-----

									f
W/O:			WO	RK ORDER CHANG	ES				<i>i</i> .
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	<u> </u>	PAR #:	Fault Categ	orv:	NCR: Yes	No DO	Δ.	Date:	
			Disposition: (
NCR:		,	WORK ORDE	R NON-CONFORMA	ANCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC inspector
									1

Picklist Print

February 4, 2010 8:50:48 AM

Work Order ID: 55898

Parent Item: Parent Item Name:

D4004-11

Strap Attach Bracket

Comments:

IPP rev A 09.12.15 new issue EC verified by:DD

Start Date: 2/04/10

Oty To Pick Issued

Qty

Start Oty: 2.00

Remaining

Required Date: 2/11/10

Required Oty: 2.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Bin Primary Item Location Last Location Route Seq ID

Unit of Measure Hand

Qty on

Date Issued

Status

40456-11-144

Purchased

No

100

Each

0.0000

0.8632

Page 1

SEAT TRACK

Dart	Aerospace	Ltd
	•	

		· · · · · · · · · · · · · · · · · · ·								3	
W/O:			WORK ORDER CHANGES								
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									,		
	,			······································	•		* 1				
		,								,	
Part No: PAR #:		PAR #:	Fault Cat	egory:	NC	R: Yes I	A :	Date:			
		Disposition: Q			QA: N/C Closed:			Date:			
NCR:			WORK OR	DER NON-CONFO	RMANCE	(NCR)				
DATE	STEP	Description of NC	Corrective Action Section B Initial Action Description			Verificat			on Approval	Approval	
DAIL	SIEF	SIEP Section A		Action Descrip Chief Eng				on C	Chief Eng	QC Inspector	
									ì		
								<u>.</u>			
1	1	1	1 1			I			(1	



